


13. Contour Drawing



Pin Symbol	Pin Symbol
1 GND	21 G5
2 GND	22 G4
3 NC	23 G3
4 Vcc	24 GND
5 Vcc	25 G2
6 Vcc	26 G1
7 Vcc	27 G0
8 NC	28 GND
9 DE	29 R5
10 GND	30 R4
11 GND	31 R3
12 GND	32 GND
13 SCL(SSEL)	33 R2
14 NC(SCK)	34 R1
15 SDA(MOSI)	35 R0
16 NC(MISO)	36 GND
17 /RST	37 GND
18 /WAKE	38 DCLK
19 /INT	39 GND
20 GND	40 GND

PIN NO.	SYMBOL
1	GND
2	VDD
3	SCL(SSEL)
4	NC(SCK)
5	SDA(MOSI)
6	NC(MISO)
7	/RST
8	/WAKE
9	/INT
10	GND

Important dimensions!

The non-specified tolerance of dimension is ±0.3mm.

